

Gin Gliders Yeti 22

Contributed by Randi Eriksen
Friday, 22 February 2008

Gin Gliders Yeti 22, Classification B

We have two flight test report for Yeti 22. The reason is we (Air Turquoise) can not provide light enough test pilot for this glider. The manufacturer must by themself find a light enough pilot who can do the tests. Air Turquoise has to supervise these tests and has also to test with their two lightest test pilots to confirm the results.

- Flight test report 1
- Flight test report 2
- Load test report
- Load test diagram
- Sticker