



## Explanation of the EN Flight test report



## Example manoeuvre no. 13 Recovery from a developed full stall



Not available and comment of test pilot

Not available doesn't mean dangerous. It means this test is not possible to do and therefore no (zero) result. Especially for tandem gliders, it is sometimes physically impossible to do the

<b>24. Any other flight procedure and/or configuration described in the user's manual</b>	<b>0</b>			
Procedure works as described	not available	0	not available	0
Procedure suitable for novice pilots	not available	0	not available	0
Cascade occurs	not available	0	not available	0
<b>25. Comments of test pilot</b>				
Comments				

The test pilot has a possibility to write a comment if the test pilot can not describe the glider good enough according to EN standard EN 926-2. *Last information of the glider.*

Flight tests are done by Air Turquoise SA / Switzerland

**para-test.com**



Air Turquoise SA  
Rue de la Poderlaz 6 | CH-1844 Villeneuve  
tel. +41 21 965 65 65 | mobile +41 79 202 52 30  
info@para-test.com